

CONTRACTORS SAFETY NOTICE

ASBESTOS

WARNING: This building may contain asbestos

These products are in many forms with different surface finishes that can hide the fact that asbestos is present. It is not a simple process to determine whether asbestos materials are present, and it is safer to assume that all materials contain asbestos unless you know for sure or it is proven otherwise that they do not.

Always be sure to check whether any asbestos is present, using the onsite asbestos register.

Before any work is carried out that may disturb unknown asbestos materials intrusive checks may be required including a Refurbishment and Demolition Survey.



Report discovery and/or damage to asbestos to:
Paul Stevenson or
Laura Houghton

Tel: 01295 263740

FIRE ACTION

If you discover a fire

	Sound the alarm
	Dial 999 to call the Fire Service
	Attack the fire if possible using the extinguishers provided
	Leave the building by the nearest route
	Your nearest Assembly Point is <input type="text" value="Staff car park"/>
	Do not stop to collect tools and equipment

SERVICE ISOLATION POINTS

 	Gas <input type="text" value="Cupboard on Drop and Dash Area"/>
	Electric <input type="text" value="Plant Room"/>
	Water <input type="text" value="Plant Room"/>

SITE RULES

	Smoking is strictly prohibited on these Premises
	All contractors must report to reception and sign in-out
	All Contractors must display Identification at all times

FIRST AID

Your nearest First Aid Kit is located

Your nearest Defibrillator is located

Your First Aider is

PREMISES CONTACTS

Responsible Premises Manager

Paul Stevenson
01295 263740

Out of Hours Emergency Contact

office@st-johns-banbury.oxon.sch.uk



The
Pope Francis Catholic
Multi Academy Company